






PMB-1029 Panel Mount Bracket and Gasket for 1029 series monitors



Description

Panel Mount Bracket and Gasket for 1029 series for Panel Mount Industrial Monitors and Touch Screens.

1. Remove two M2.6*5 screws from the bottom of the L bracket.
2. Place the monitor into the PMB-1029 Panel Mount Bracket.
3. Secure the monitor to the PMP-1029 Panel Mount Bracket by fastening two M2.6*5 screws into the left side, two M2.6*5 into the right side, and re-install the two bottom M2.6*5 screws that you removed from step one.
4. Create a shortcut on the wall or panel where you want to mount the monitor and install the monitor into the cutout.
5. Install the eight mounting hardware into the PMB-1029 Panel Mount Bracket as shown in the diagram below.
6. Fasten the eight M4*20 screws to secure the PMB-1029 Panel Mount Bracket onto the wall or panel.

Related Products:

1029GNH

1029CNH

Function Diagram

Panel Mount Bracket and Gasket for 1029 series monitors

Image not found

<http://www.xenarcdirect.com/image.php?type=FD&id=17735>

Package Contents

Panel Mount Brackets Panel Mount Gasket