
PMB-1029 Panel Mount Bracket and Gasket for 1029 series monitors



Description

Panel Mount Bracket and Gasket for 1029 series for Panel Mount Industrial Monitors and Touch Screens.

- 1. Remove two M2.6*5 scres from the bottom of the L bracket.
- 2. Place the monitor into the PMB-1029 Panel Mount Bracket.
- 3. Secure teh monitor to the PMP-1029 Panel Mount Bracket by fastening two M2.6*5 screws into the left side, two M2.6*5 into the right side, and re-install the two bottom M2.6*5 screws that you removed from step one.
- 4. Create a shortcut on the wall or panel where you want to mount the monitor and install the monitor into the cutout.
- 5. Install the eight mounting hardware into the PMB-1029 Panel Mount Bracket as shown in the diagram below.
- 6. Fasten the eight M4*20 screws to secure teh PMB-1029 Panel Mount Bracket onto the wall or panel.

Related Products:

1029GNH

1029CNH

Function Diagram

Panel Mount Bracket and Gasket for 1029 series monitors

Image not found http://www.xenarcdirect.com/image.php?type=FD&id=17735

Package Contents

Panel Mount Brackets Panel Mount Gasket