






# **PMB-1029 Panel Mount Bracket and Gasket for 1029 series monitors**



## Description

### **Panel Mount Bracket and Gasket for 1029 series for Panel Mount Industrial Monitors and Touch Screens.**

1. Remove two M2.6\*5 screws from the bottom of the L bracket.
2. Place the monitor into the PMB-1029 Panel Mount Bracket.
3. Secure the monitor to the PMP-1029 Panel Mount Bracket by fastening two M2.6\*5 screws into the left side, two M2.6\*5 into the right side, and re-install the two bottom M2.6\*5 screws that you removed from step one.
4. Create a shortcut on the wall or panel where you want to mount the monitor and install the monitor into the cutout.
5. Install the eight mounting hardware into the PMB-1029 Panel Mount Bracket as shown in the diagram below.
6. Fasten the eight M4\*20 screws to secure the PMB-1029 Panel Mount Bracket onto the wall or panel.

## **Related Products:**

1029GNH

1029CNH

## Function Diagram

Panel Mount Bracket and Gasket for 1029 series monitors

Image not found  
<http://www.xenarcdirect.com/image.php?type=FD&id=17735>

## Package Contents

Panel Mount Brackets Panel Mount Gasket